

Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment

GOVERNMENT NOTICE No. 930 Published On. 23/10/2020

THE VALUE ADDED TAX ACT,
(CAP. 148)

ORDER

(Made under section 6 (2))

THE VALUE ADDED TAX (EXEMPTION) (REHABILITATION OF MV VICTORIA AT
MWANZA BRANCH) (M/S KTMI CO. LTD IN JOINT VENTURE WITH YUKO'S
ENTERPRISES E.A LTD) AMENDMENT ORDER, 2020

Citation
G.N No.
503 of 2020

1. This Order may be cited the Value Added Tax (Exemption) (Rehabilitation of MV Victoria at Mwanza Branch) (M/S KTMI Co. Ltd in Joint Venture with Yuko's Enterprises E.A Ltd) Amendment Order, 2020 and shall be read as one with the Value Added Tax (Exemption) (Rehabilitation of MV Victoria at Mwanza Branch) (M/S KTMI Co. Ltd in Joint Venture with Yuko's Enterprises E.A Ltd) Order, 2019 hereinafter referred to as "the principal Order".

Amendment of
paragraph 4

2. The principal Order is amended in paragraph 4 by deleting the expiry date and substituting for it the 29th day of January, 2021.

Amendment of
Schedule

3. The principal Order is amended in the Schedule by deleting Schedule B and substituting for it the following-

SCHEDULE GOODS AND SERVICES				
S/N	ITEM DESCRIPTION	QUANTI TY (QTY)	UNIT OF MEASUR E	PLACE OF PURCHASE OF ITEMS (Local or Imported)

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

1	HYDRAULIC ELECTRICAL CRANE (5T/ 8.5M)	1	PCS	Imported
2	SLANT WASHER	450	KGS	Imported
3	CANVAS DUCT	159	KGS	Imported
4	CABLE & PLUG	1890	KGS	Imported
5	RATCHET HANDLE	25	PCS	Imported
6	FLEXIBLE HANDLE	25	PCS	Imported
7	SOCKET (8, 10, 12, 13MM) 4 TYPES	28	PCS	Imported
8	SOCKET (15, 17, 19, 22, 27MM) 5 TYPES	42	PCS	Imported
9	EXTENSION BAR 4 TYPES	28	PCS	Imported
10	COMBINATION WRENCH 13 TYPES	46	PCS	Imported
11	FEELER GAUGE	8	PCS	Imported
12	L-WRENCH 13TYPES	56	PCS	Imported
13	ADJUSTABLE WRENCH	62	PCS	Imported
14	DRIVER	76	PCS	Imported
15	PLASTIC HAMMER	38	PCS	Imported
16	FILTER WRENCH	12	PCS	Imported
17	NIPPER	12	PCS	Imported
18	WISE PLIER	12	PCS	Imported
19	SNAP RING PLIER	12	PCS	Imported
20	TOOL BOX	32	PCS	Imported
21	PISTON RING SET	50	PCS	Imported
22	NOZZLE, PISTON COOLING	18	PCS	Imported
23	KIT, EXHAUST VALVE	39	PCS	Imported
24	KIT, INTAKE VALVE	38	PCS	Imported
25	INJECTOR	12	PCS	Imported
26	O-RING SEAL, INJECTOR	12	PCS	Imported
27	O-RING SEAL, INJECTOR	12	PCS	Imported
28	O-RING SEAL, INJECTOR	12	PCS	Imported
29	MAIN BEARING	56	PCS	Imported
30	BEARING, CON ROD	24	PCS	Imported
31	PIN, PISTON	32	PCS	Imported
32	BUSHING	32	PCS	Imported
33	DOWEL, PIN	41	PCS	Imported
34	WASHER, PLAIN	41	PCS	Imported
35	SEAL, RECTANGULAR RING	12	PCS	Imported
36	FUEL WATER	18	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

	SEPARATOR			
37	FUEL FILTER	18	PCS	Imported
38	COOLANT FILTER	18	PCS	Imported
39	LUBE OIL FILTER	18	PCS	Imported
40	AIR CLEANER	8	PCS	Imported
41	UPPER GASKET KIT	3	PCS	Imported
42	LOWER GASKET KIT	3	PCS	Imported
43	FUSE	6	PCS	Imported
44	DIODE	15	PCS	Imported
45	FUSE PULLER	3	PCS	Imported
46	FLEXIBLE HANDLE	34	PCS	Imported
47	EXTENSION BAR 4 TYPES	35	PCS	Imported
48	COMBINATION WRENCH 13 TYPES	36	PCS	Imported
49	ADJUSTABLE WRENCH	12	PCS	Imported
50	DRIVER	15	PCS	Imported
51	WISE PLIER	6	PCS	Imported
52	SNAP RING PLIER	16	PCS	Imported
53	BALL BEARING	56	PCS	Imported
54	GASKET, CYLINDER HEAD	256	PCS	Imported
55	GASKET, VALVE COVER	96	PCS	Imported
56	FAN BELT	8	PCS	Imported
57	FILTER, FUEL	36	PCS	Imported
58	L.O FILTER	36	PCS	Imported
59	AIR FILTER	36	PCS	Imported
60	FUEL WATER SEPARATOR	36	PCS	Imported
61	LOWER GASKET KIT	21	PCS	Imported
62	SPARE PART BOX	86	PCS	Imported
63	FUSE	46	PCS	Imported
64	DIODE	55	PCS	Imported
65	FUSE PULLER	15	PCS	Imported
66	FUSE 25A	55	PCS	Imported
67	FUSE 10A	55	PCS	Imported
68	FUSE 5A	55	PCS	Imported
69	RELAY	48	PCS	Imported
70	OIL FILTER ELEMENT	48	PCS	Imported
71	O-RING FOR HEAT EXCHANGER	56	PCS	Imported
72	SEAL SET FOR FILTER	16	PCS	Imported
73	SPARE OIL PUMP	17	PCS	Imported
74	SPARE BEARING SET	17	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

75	TILE	7,860	KGS	Imported
76	TILE	2,775	PCS	Imported
77	TILE 4" CUTTER FOR TILES	80	PCS	Imported
78	TILE CEMENT (72/20KG BAG) & TILE GROUTING (15/20KG BAG)	6,780	KGS	Imported
79	PUTTY 25KG	1,685	KG	Imported
80	SELF-LEVELING POWDER	8,400	KGS	Imported
81	DECK FLOORING MATERIAL	28,500	KGS	Imported
82	TOP POWDER	3,500	KGS	Imported
83	PRIMER POWDER	5,640	KGS	Imported
84	MIXED PERLITE	14,500	KGS	Imported
85	LATEX, 20KG/CAN	5,760	KGS	Imported
86	WIRE MESH	3,510	KGS	Imported
87	SL PRIMER BONDING COAT	1,120	KGS	Imported
88	FL. CEILING LIGHT IEC 1P56, AC220V,50HZ,18WX1 (FS210W-SG55IW)	118	PCS	Imported
89	FL. CEILING LIGHT IEC 1P56, AC220V,50HZ,36WX1 (FS410W-SG55IW)	110	PCS	Imported
90	FL. CEILING LIGHT IEC 1P56, AC220V,50HZ,36WX1 (FS410W-SG55IW)	128	PCS	Imported
91	CEILING PANEL	3,589	KGS	Imported
92	TOP PROFILE	1,120	KGS	Imported
93	SIDE RUNNER P-003, 1.0T X 3,000L, GALVANIZED	1,890	KGS	Imported
94	JOINT PROFILE P-002, 0.6T X 3,000L, RAL 900	1,352	KGS	Imported
95	EDGE COVER P-026, 1.0T X 3,000L, RAL 9003	2,561	KGS	Imported
96	CAP PROFILE P-167, 0.6T X 2,400L, GALVANIZED	4,680	KGS	Imported
97	IN CORNER PROFILE P- 111, 0.6T X 2,400L, GALVANIZED	3,561	KGS	Imported
98	OUT CORNER PROFILE, GALVANIZED	1,234	KGS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

99	PVC SKIRT BLACK	987	KGS	Imported
100	PVC FILM - HYUNDAI L&C INTERIOR FILM BODAQ	1,125	KGS	Imported
101	VINYL TILE HYUNDAI L&C GOLD TILE CLASSIC,	1,872	KGS	Imported
102	VINYL SHEET	897	KGS	Imported
103	PAINT TOOL - ROLLER STICK	50	PCS	Imported
104	GLUE FOR VINYL SHEET - W-510NF BOND, 10KG/CAN	780	KGS	Imported
105	STAINLESS WEATHER DOOR	60	PCS	Imported
106	MARINE CLOCK QUARTZ, MARINE TYPE, 3EA	6	PCS	Imported
107	HAND GRIP,	160	PCS	Imported
108	PAPER HOLDER	80	PCS	Imported
109	TOWEL BAR,	80	PCS	Imported
110	TOWEL BAR,	80	PCS	Imported
111	SOAP DISH,	185	PCS	Imported
112	COAT HOOK FOR TOILET,	185	PCS	Imported
113	ROLLER BLIND 700X1,800MM,	1,520	KGS	Imported
114	HONEYCOMB, 16EA/BOX	6,851	KGS	Imported
115	LOCKSET ANSI GRADE 2, ONE(1) MASTER KEY SYSTEM, AGL- 1000(LIGHT DUTY TYPE), 30EA/BOX	120	PCS	Imported
116	LOCKSET ANSI GRADE 2, ONE(1) MASTER KEY SYSTEM, AGL-1000(LIGHT DUTY TYPE), 14EA/BOX	14	PCS	Imported
117	PAD LOCK STAINLESS OR BRASS, ONE(1) MASTER KEY SYSTEM, 26EA/BOX	152	PCS	Imported
118	SILICONE SEALANT 300ML, TUBE, WHITE 50EA/2BOX	100	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

119	MIXING MACHINE EV52, 1300W	2	PCS	Imported
120	TAPE 3M, 1200MM X 50MM	139	KGS	Imported
121	CAP NUT	980	KGS	Imported
122	INTER SHAFT BEARING	4	PCS	Imported
123	PROPELLER KEY	4	PCS	Imported
124	COUPLING KEY	4	PCS	Imported
125	COUPLING NUT	4	PCS	Imported
126	INTERMEDIATE SHAFT(VICTORIA)	4	PCS	Imported
127	RUDDER BUSH	4	PCS	Imported
128	COUPLING(PROPELLER SHAFT/PORT)	4	PCS	Imported
129	COUPLING(PROPELLER SHAFT/STB'D)	4	PCS	Imported
130	COUPLING(REDUCTION GEAR/PORT)	4	PCS	Imported
131	COUPLING(REDUCTION GEAR/STB'D)	4	PCS	Imported
132	PACKING(3/4"---10M)	4	PCS	Imported
133	PACKING(1/2"---10M)	4	PCS	Imported
134	BEARING COVER(AFT/PORT & STB'D)	4	PCS	Imported
135	BEARING COVER(MID/PORT & STB'D)	4	PCS	Imported
136	COUPLING BOLT(PROPELLER SHAFT)	40	KGS	Imported
137	COUPLING BOLT(REDUCTION GEAR)	72	KGS	Imported
138	COUPLING BOLT(INTER SHAFT)	20	KGS	Imported
139	PROPELLER SPANNER	4	PCS	Imported
140	COUPLING SPANNER(PROPELLER SHAFT)	4	PCS	Imported
141	COUPLING SPANNER(REDUCTION GEAR)	4	PCS	Imported
142	PROPELLER SPANNER(OUT)	4	PCS	Imported
143	ELECTRODE	5460	KGS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

144	MICROPHONE(HDM-012C)	10	PCS	Imported
145	POWER PACK (W) 22KW	8	PCS	Imported
146	LED FLOOD LIGHT_B (DMX512, RGB, 24V, 36W)	115	PCS	Imported
147	SMPS IP67, 24V, 100W	56	PCS	Imported
148	SMPS IP67, 24V, 150W	56	PCS	Imported
149	OUTSIDE SMPS BOX (TERMINAL BLOCK) (300X300X210MM)	52	PCS	Imported
150	SPLITTER (5-PIN XLR INPUT/OUTPUT DMX-RDM E1.20 SPLITTER)	51	PCS	Imported
151	DMXCONTROLLER (WALL MOUNTED, 1024 DMX CHANNEL, 106X146X10MM)	16	PCS	Imported
152	LINEAR FLOOD LIGHT (LED 36W, DC24V, (L)1000 x (W)52 x (H)33 mm, WHITE (5000K))	16	PCS	Imported
153	DMX MAKER CABLE (1 PAIR, 24 AWG, STP (SHIELDED TWIST PAIR CABLE))	300	PCS	Imported
154	OUTSIDE N/LECS03	10	PCS	Imported
155	COMMISSIONING PROCEDURE	6	PCS	Imported
156	FIRE ALARM BELL W/LAMP (DC24V) WEATHER PROOF	21	PCS	Imported
157	CONVENTIONAL FIRE CONTROL PANEL 10 ZONES	1	PCS	Imported
158	OPTICAL SMOKE DETECTOR INCLUDE BASE	2	PCS	Imported
159	FIXED TEMPERATURE HEAT DETECTOR (65°C) INCLUDE BASE	2	PCS	Imported
160	DECK HEAD MOUNT WEATHER PROOF	4	PCS	Imported
161	MANUAL CALL POINT (W/CG) WEATHER PROOF	26	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
GN. No. 930 (Contd.)*

162	HOSE BOX	22	PCS	Imported
163	HOSE W/COUPLING JIS 40A*15M	22	PCS	Imported
164	SPRAY/JET NOZZLE JIS 40A*19MM	22	PCS	Imported
165	SPANNER FOR COUPLING JIS 40A	22	PCS	Imported
166	OPTICAL SMOKE DETECTOR DBM-CSD100	1	PCS	Imported
167	FIXED TEMPERATURE HEAT DETECTOR (65°C) DBM-CHD165	1	PCS	Imported
168	MANUAL CALL POINT (W/CG) WEATHER PROOF	1	PCS	Imported
169	FUSE 1A	2	PCS	Imported
170	FUSE 2A	2	PCS	Imported
171	END OF RESISTER 10kΩ, 1/4W	10	PCS	Imported
172	BOX FOR SPARES & TEST EQUIPMENT 3HO	1	PCS	Imported
173	AEROSOL SMOKE TESTER CAN M8	1	PCS	Imported
174	HEAT DETECTOR TESTER DRYER	1	PCS	Imported
175	CALL POINT TEST KEY	6	PCS	Imported
176	FIRE HYDRANT VALVE	65	PCS	Imported
177	CO ₂ WELDING MACHINE	1	PCS	Imported
178	MAGNETIC DRILL (UDT ME-4000)	1	PCS	Imported
179	WELDING ROD 1.4MM*15KG	3603	KGS	Imported
180	WASTE RAG(4.5 KG)	250	KGS	Imported
181	SHRINK TUBE 3(Y/G) G	300	PCS	Imported
182	SHRINK TUBE 6(Y/G)	100	PCS	Imported
183	SHRINK TUBE 9(Y/G)	100	PCS	Imported
184	SHRINK TUBE 12(Y/G)	100	PCS	Imported
185	SHRINK TUBE 16(Y/G)	100	PCS	Imported
186	PVC MOLD 1*200	2500	KGS	Imported
187	PVC MOLD 1*120	2500	KGS	Imported
188	PVC MOLD 1*100	2500	KGS	Imported
189	PVC MOLD 1*100	2500	KGS	Imported
190	PVC MOLD 1*70	10	PCS	Imported
191	ELECTRIC MOTOR F181 5.5KW 4P 1/5 380V 50HZ	16	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

192	WASTE RAG(4.5 KG)	5	PCS	Imported
193	CARGO HOLD LADDER	8	PCS	Imported
194	ACCOMMODATION LADDER	1	PCS	Imported
195	UPPER PLATFORM & TURN TABLE	1	PCS	Imported
196	STOWING DAVIT	1	PCS	Imported
197	STOPPER FOR STOWING DAVIT	1	PCS	Imported
198	REST	3	PCS	Imported
199	LASHING SOCKET & PAD	6	PCS	Imported
200	SPINDLE PIPE	1	PCS	Imported
201	SHAFT HOLDER	4	PCS	Imported
202	GUIDE SHEAVE SET	3	PCS	Imported
203	STANCHION STAND	1	PCS	Imported
204	FALL ROPE	1	PCS	Imported
205	ANTENNA	2	PCS	Imported
206	WINCH & MOTOR ASS'Y/SEAT	1	PCS	Imported
207	STARTER	1	PCS	Imported
208	PROTECTION BOX	1	PCS	Imported
209	LIMIT SWITCH(2MSAL)	2	PCS	Imported
210	EMERGENCY STOP BUTTON	1	PCS	Imported
211	INDICATING LAMP	1	PCS	Imported
212	BULB	3	PCS	Imported
213	GLOVE	1	PCS	Imported
214	FUSE CASE	1	PCS	Imported
215	FUSE ELEMENT	6	PCS	Imported
216	AIR VENT 5K-50A	2	PCS	Imported
217	AIR VENT 5K-65A	19	PCS	Imported
218	CONSOLE	1	PCS	Imported
219	CONSOLE	2	PCS	Imported
220	TERMINAL LUG 95X10	120	PCS	Imported
221	TERMINAL LUG 70X10	100	PCS	Imported
222	TERMINAL LUG 50X10	70	PCS	Imported
223	TERMINAL LUG 38X10	70	PCS	Imported
224	TERMINAL LUG 25X10	100	PCS	Imported
225	TERMINAL LUG 16X10	100	PCS	Imported
226	TERMINAL LUG 2.5X5	100	PCS	Imported
227	TERMINAL LUG 4X6	100	PCS	Imported
228	TERMINAL LUG 6X6	100	PCS	Imported
229	TERMINAL LUG 10X5	100	PCS	Imported
230	TERMINAL LUG 10X6	100	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

231	TERMINAL LUG 16X6	100	PCS	Imported
232	TERMINAL LUG 16X8	100	PCS	Imported
233	PIN TERMINAL LUG 2.5	100	PCS	Imported
234	PIN TERMINAL LUG 4	100	PCS	Imported
235	PIN TERMINAL LUG 6	100	PCS	Imported
236	PIN TERMINAL LUG 10	100	PCS	Imported
237	PIN TERMINAL LUG 16	100	PCS	Imported
238	TUBE 2.5/4/6/10/16/25/35/50	100	PCS	Imported
239	TUBE 70/95	100	PCS	Imported
240	VOLTAGE TRANSFORMER PT 460/115V	2	PCS	Imported
241	TR 380V/220X(60VA)	1	PCS	Imported
242	TR 260V/26V(500VA)	1	PCS	Imported
243	TR 220V/26V(100VA)	1	PCS	Imported
244	CONTROL TRANSFORMER TR 400V/230V(500VA)	1	PCS	Imported
245	CONTROL RELAYS MR4 220V 50HZ	3	PCS	Imported
246	CONTACTOR MC22B 220V 50HZ	1	PCS	Imported
247	CONTACTOR NC100A 220V50HZ	1	PCS	Imported
248	CONTACTOR MC65A 220V 50HZ	1	PCS	Imported
249	CONTACTOR DMC65 220V 50HZ	1	PCS	Imported
250	CONTACTOR DMC65 380V 50HZ	1	PCS	Imported
251	MAGNETIC CONTRACTOR DMC 65 380V 50HZ	1	PCS	Imported
252	MAGNETIC CONTRACTOR DMC 65 380V 50HZ	1	PCS	Imported
253	MAGNETIC CONTRACTOR DMC40B 380V 50HZ	1	PCS	Imported
254	MAGNETIC CONTRACTOR DMD40B DC24V	1	PCS	Imported
255	V-METER(AC300V)	1	PCS	Imported
256	HZ-METER(45-55HZ) (80X80)	1	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

257	POWER RELAY DC24V	2	PCS	Imported
258	A-METER(60*60) 300%	1	PCS	Imported
259	MCCB ACCESSORY DEVICE UVT 100GM(AC440V)	1	PCS	Imported
260	MCCB ACCESSORY DEVICE UVT 380V	1	PCS	Imported
261	MCCB ACCESSORY DEVICE SHT LWT IN 380V-440V	1	PCS	Imported
262	MCCB ACCESSORY DEVICE SHT LWT IN AC/DC 200-250V	1	PCS	Imported
263	FUSE 3A	20	PCS	Imported
264	FUSE 20A	20	PCS	Imported
265	FUSE 30A	15	PCS	Imported
266	PILOT LAMP PL 220V	4	PCS	Imported
267	PILOT LAMP PBL 220V	2	PCS	Imported
268	PILOT LAMP PB1A1B	1	PCS	Imported
269	PILOT LAMP S/S 1A1B	1	PCS	Imported
270	PILOT LAMP PL 24V	1	PCS	Imported
271	WASTE RAG (4.5 KG)	10	PCS	Imported
272	MOORING PIPE	1	PCS	Imported
273	ELECTRIC HORN	1	PCS	Imported
274	MAIN UNIT SPEAKER	1	PCS	Imported
275	ELECTRIC SPEAKER	1	PCS	Imported
276	SPEAKER	1	PCS	Imported
277	RADAR MANUAL	2	PCS	Imported
278	EARTH BAR	2	PCS	Imported
279	MONOTOR CABLE	4	PCS	Imported
280	FUSE	6	PCS	Imported
281	MAGNETIC COMPASS	2	PCS	Imported
282	MOTOR(F.W HYDRAULIC UNIT) TYPE : PBI-404MA(AUTO START-STOP) Ø 32 X Ø25 X 6/4M3/H X 33/45M, 1Ø 1500W 2P(2950RPM) 220V 50HZ	3	PCS	Imported
283	INDICATOR LOCK	74	PCS	Imported
284	WASTE RAG(4.5KG)	10	PCS	Imported
285	COTTON GLOVES	1200	PCS	Imported
286	MASK	240	PCS	Imported
287	SIKAFLEX-221	20	PCS	Imported
288	SIKA GUN	1	PCS	Imported
289	MANHOLE COVER(OL1-	15	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

	AC)			
290	F.O PURIFIER(HDF-600)	2	PCS	Imported
291	SPARE FILTER(3 YEARS)	9	PCS	Imported
292	VENTILATOR FAN E/R FAN(2.2KW)	4	PCS	Imported
293	VENTILATOR FAN OFFICER CABIN TOILET(0.75KW)	1	PCS	Imported
294	VENTILATOR FAN MAIN GALLEY(0.75KW)	1	PCS	Imported
295	VENTILATOR FAN 2 CLASS (1)(0.75KW)	1	PCS	Imported
296	VENTILATOR FAN 2 CLASS (2)(0.75KW)	1	PCS	Imported
297	VENTILATOR FAN UPPER DECK MIDDLE(0.75KW)	1	PCS	Imported
298	VENTILATOR FAN THIRD CLASS(0.75KW)	1	PCS	Imported
299	VENTILATOR FAN OFFICER CABIN(1) (0.75KW)	1	PCS	Imported
300	VENTILATOR FAN TOILET(0.75KW)	1	PCS	Imported
301	VENTILATOR FAN 1 CLASS(2.2KW)	1	PCS	Imported
302	VENTILATOR FAN MAIN DECK CABIN(2.2KW)	1	PCS	Imported
303	VENTILATOR FAN 1 CLASS CABIN TOILET(0.75KW)	1	PCS	Imported
304	ZINC ANODE(A-9)	26	PCS	Imported
305	ZINC ANODE(A-4)	23	PCS	Imported
306	CABLE 0.6/1KV TPYCY 25SQ*3C	250	PCS	Imported
307	STEEL FRAME	865.0	KGS	Imported
308	PEDESTAL	596.0	KGS	Imported
309	PEDESTAL HEAD	879.0	KGS	Imported
310	RUBBER LIFTER	752.0	KGS	Imported
311	SCREW	1952.0	KGS	Imported
312	PLASTIC GASKET	20.0	KGS	Imported
313	ALARM PANEL	50.0	PCS	Imported
314	CO2 WELDING ROD 1.4MM	450.0	PCS	Imported
315	PASSENGER SPACE 1.5KW	50.0	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

316	SPONGE	60.0	PCS	Imported
317	VALVE ANGLE 5K25A SDNR	2	PCS	Imported
318	VALVE GLOBE 5K25A SDNR	2	PCS	Imported
319	VALVE S-TYPE 5K25A WATER STRINER	1	PCS	Imported
320	VALVE ANGLE 5K65A	3	PCS	Imported
321	VALVE GLOBE V 5K65A5K25A SDNR	1	PCS	Imported
322	VALVE GLOBE 30K20A SF440 RF	2	PCS	Imported
323	VALVE GLOBE 30K15A SF440 RF	3	PCS	Imported
324	VALVE GLOBE 30K25A SDNR SF440 RF	3	PCS	Imported
325	VALVE GLOBE 30K25A SF440 RF	2	PCS	Imported
326	VALVE 30K25A Y-STRAINER SC480	1	PCS	Imported
327	30K25A PRESSURE REDUCING VALVE	1	PCS	Imported
328	ANGLE 30K15A 25A SAFETY VALVE SC480	1	PCS	Imported
329	VALVE GLOBE 16K15A	3	PCS	Imported
330	VALVE GLOBE 10K15A HOSE GLOBE	2	PCS	Imported
331	ANGLE 16K15A	2	PCS	Imported
332	VALVE GLOBE 16K15A SDNR	2	PCS	Imported
333	ANGLE 10K50A	3	PCS	Imported
334	ANGLE 5K80A SDNR	1	PCS	Imported
335	ANGLE 5K40A	3	PCS	Imported
336	ANGLE 5K80A SDNR	1	PCS	Imported
337	VALVE 5K65A WATER STRAINER	3	PCS	Imported
338	VALVE GLOBE 5K65A	3	PCS	Imported
339	ANGLE 5K32A	2	PCS	Imported
340	VALVE GLOBE 5K25A SDNR	2	PCS	Imported
341	VALVE GLOBE 5K15A	2	PCS	Imported
342	VALVE GLOBE 5K20A	5	PCS	Imported
343	VALVE GLOBE 5K15A SDNR	5	PCS	Imported
344	VALVE 10K15A EMCY SHUT OFF	1	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

345	VALVE GLOBE 5K50A SDNR	3	PCS	Imported
346	VALVE GLOBE 5K50A	1	PCS	Imported
347	VALVE 5K15A SELF CLOSING	1	PCS	Imported
348	VALVE GLOBE 5K-40A	1	PCS	Imported
349	VALVE 16K-32A SDNR	2	PCS	Imported
350	VALVE 16K-40A	2	PCS	Imported
351	VALVE 10K15A HOSE GLOBE	2	PCS	Imported
352	VALVE GLOBE 5K-40A SDNR	2	PCS	Imported
353	ANGLE 5K65 SDNR	2	PCS	Imported
354	VALVE GLOBE 5K15A SDNR	2	PCS	Imported
355	VALVE GLOBE 5K15A	3	PCS	Imported
356	VALVE 5K40A WATER STRAINER	3	PCS	Imported
357	VALVE 5K50A OIL STRAINER	1	PCS	Imported
358	VALVE SPECTACLE FLG 5K-40A	1	PCS	Imported
359	VALVE GATE 5K50A , F7363	4	PCS	Imported
360	VALVE ANGLE 5K 25A	2	PCS	Imported
361	VALVE ANGLE 5K 20A	2	PCS	Imported
362	VALVE GLOBE 5K 25A	1	PCS	Imported
363	VALVE GLOBE 5K 25A SDNR	1	PCS	Imported
364	VALVE GLOBE 5K 40A	1	PCS	Imported
365	VALVE GLOBE 5K 15A	1	PCS	Imported
366	VALVE GLOBE 5K 15A SDNR	1	PCS	Imported
367	STAINLESS STEEL WIRE ROPE	2	PCS	Imported
368	WIRE SLEEV	400	PCS	Imported
369	LEVEL GUAGE	1	PCS	Imported
370	JUNCTION BOX	50	PCS	Imported
371	GASKET NON-ASB' / RF-TYPE / 15A-5K	132	PCS	Imported
372	GASKET NON-ASB' / RF-TYPE / 15A-10K	48	PCS	Imported
373	GASKET/SPIRAL WOUND /15A-30K	12	PCS	Imported
374	GASKET NON-ASB'/ RF-TYPE/20A-5K	129	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

375	GASKET/SPIRAL WOUND/20A-30K	16	PCS	Imported
376	GASKET NON-ASB' / RF- TYPE / 25A-5K	100	PCS	Imported
377	GASKET NON-ASB' / RF- TYPE / 25A-10K	45	PCS	Imported
378	GASKET /SPIRAL WOUND/25A-30K	25	PCS	Imported
379	GASKET NON-ASB' / RF- TYPE / 25A-DIN PN10	1	PCS	Imported
380	GASKET NON-ASB' / RF- TYPE / 32A-5K	25	PCS	Imported
381	GASKET NON-ASB' / RF- TYPE / 32A-10K	6	PCS	Imported
382	GASKET NON-ASB' / RF- TYPE / 40A-5K	58	PCS	Imported
383	GASKET NON-ASB' / RF- TYPE / 40A-10K	15	PCS	Imported
384	GASKET NON-ASB' / RF- TYPE / 40A-DIN PN10	5	PCS	Imported
385	GASKET NON-ASB' / RF- TYPE / 50A-5K	50	PCS	Imported
386	GASKET NON-ASB' / RF- TYPE / 50A-10K	10	PCS	Imported
387	GASKET NON-ASB' / RF- TYPE / 50A-DIN PN10	2	PCS	Imported
388	GASKET NON-ASB' / RF- TYPE / 65A-5K	45	PCS	Imported
389	GASKET NON-ASB' / RF- TYPE / 65A-10K	8	PCS	Imported
390	GASKET NON-ASB' / RF- TYPE / 65A-DIN PN10	7	PCS	Imported
391	GASKET NON-ASB' / RF- TYPE / 80A-5K	22	PCS	Imported
392	GASKET NON-ASB' / RF- TYPE / 80A-10K	18	PCS	Imported
393	GASKET NON-ASB' / RF- TYPE / 80A-DIN PN10	2	PCS	Imported
394	GASKET NON-ASB' / RF- TYPE/125A-5K	3	PCS	Imported
395	GASKET NON-ASB' / RF- TYPE /125A-DIN PN10	3	PCS	Imported
396	HEX. BOLT/NUT / SS400/ELECT / M10*30 / 15A-5K	528	PCS	Imported
397	HEX. BOLT/NUT /	192	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
GN. No. 930 (Contd.)*

	SS400/ELECT / M10*35 / 20A-5K			
398	HEX. BOLT/NUT / SS400/ELECT / M10*35 / 25A-5K	48	PCS	Imported
399	HEX. BOLT/NUT / SS400/ELECT / M12*40 / 15A-10K	516	PCS	Imported
400	HEX. BOLT/NUT / SS400/ELECT / M12*40 / 32A-5K	64	PCS	Imported
401	HEX. BOLT/NUT / SS400/ELECT / M12*40 / 40A-5K	400	PCS	Imported
402	HEX. BOLT/NUT / SS400/ELECT / M12*45 / 50A-5K	180	PCS	Imported
403	HEX. BOLT/NUT / SS400/ELECT / M12*45 / 65A-5K	100	PCS	Imported
404	HEX. BOLT/NUT / SS400/ELECT / M16*45 / 25A-10K	4	PCS	Imported
405	HEX. BOLT/NUT / SS400/ELECT / M16*45 / 25A-DIN	100	PCS	Imported
406	HEX. BOLT/NUT / SS400/ELECT / M16*45 / 80A-5K	24	PCS	Imported
407	HEX. BOLT/NUT / SS400/ELECT / M16*50 / 32A-10K	232	PCS	Imported
408	HEX. BOLT/NUT / SS400/ELECT / M16*50 / 40A-10K	60	PCS	Imported
409	HEX. BOLT/NUT / SS400/ELECT / M16*50 / 40A-DIN	20	PCS	Imported
410	HEX. BOLT/NUT / SS400/ELECT / M16*50 / 50A-10K	200	PCS	Imported
411	HEX. BOLT/NUT / SS400/ELECT / M16*50 / 50A-DIN	40	PCS	Imported
412	HEX. BOLT/NUT / SS400/ELECT / M16*50 /	8	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
GN. No. 930 (Contd.)*

	125A-5K			
413	HEX. BOLT/NUT / SS400/ELEC'T / M16*50 / 125A-DIN	180	PCS	Imported
414	HEX. BOLT/NUT / SS400/ELEC'T / M16*55 / 65A-10K	32	PCS	Imported
415	HEX. BOLT/NUT / SS400/ELEC'T / M16*55 / 65A-DIN	28	PCS	Imported
416	HEX. BOLT/NUT / SS400/ELEC'T / M16*55 / 80A-10K	88	PCS	Imported
417	HEX. BOLT/NUT / SS400/ELEC'T / M16*55 / 80A-DIN	144	PCS	Imported
418	HEX. BOLT/NUT / SS400/ELEC'T / M16*60 / 15A-30K	16	PCS	Imported
419	HEX. BOLT/NUT / SS400/ELEC'T / M16*60 / 20A-30K	24	PCS	Imported
420	HEX. BOLT/NUT / SS400/ELEC'T / M16*60 / 25A-30K	24	PCS	Imported
421	U-BOLT/2NUT / SS400/ELEC'T / 15A / B- TYPE	264	PCS	Imported
422	U-BOLT/2NUT / SS400/ELEC'T / 15A / B- TYPE	96	PCS	Imported
423	U-BOLT/2NUT / SS400/ELEC'T / 15A / B- TYPE	24	PCS	Imported
424	U-BOLT/2NUT / SS400/ELEC'T / 20A / B- TYPE	258	PCS	Imported
425	U-BOLT/2NUT / SS400/ELEC'T / 20A / B- TYPE	32	PCS	Imported
426	U-BOLT/2NUT / 25A / B- TYPE / 25A-5K	200	PCS	Imported
427	U-BOLT/2NUT / 25A / B- TYPE / 25A-10K	90	PCS	Imported
428	U-BOLT/2NUT / 25A / B- TYPE / 25A-30K	50	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

429	U-BOLT/2NUT / 25A / B-TYPE / 25A-DIN	2	PCS	Imported
430	U-BOLT/2NUT / 32A / B-TYPE / 32A-5K	50	PCS	Imported
431	U-BOLT/2NUT / 32A / B-TYPE / 32A-10K	12	PCS	Imported
432	U-BOLT/2NUT / 40A / B-TYPE / 40A-5K	116	PCS	Imported
433	U-BOLT/2NUT / 40A / B-TYPE / 40A-10K	30	PCS	Imported
434	U-BOLT/2NUT / 40A / B-TYPE / 40A-DIN	10	PCS	Imported
435	U-BOLT/2NUT / 50A / B-TYPE / 50A-5K	100	PCS	Imported
436	U-BOLT/2NUT / 50A / B-TYPE / 50A-10K	20	PCS	Imported
437	U-BOLT/2NUT / 50A / B-TYPE / 50A-DIN	4	PCS	Imported
438	U-BOLT/2NUT / 65A / B-TYPE / 65A-5K	90	PCS	Imported
439	U-BOLT/2NUT / 65A / B-TYPE / 65A-10K	16	PCS	Imported
440	U-BOLT/2NUT / 65A / B-TYPE / 65A-DIN	14	PCS	Imported
441	U-BOLT/2NUT / 80A / B-TYPE / 80A-5K	44	PCS	Imported
442	U-BOLT/2NUT / 80A / B-TYPE / 80A-10K	36	PCS	Imported
443	U-BOLT/2NUT / 80A / B-TYPE / 80A-DIN	4	PCS	Imported
444	U-BOLT/4NUT / 125A / A-TYPE / 125A-5K	6	PCS	Imported
445	U-BOLT/4NUT / 125A / A-TYPE / 125A-DIN	6	PCS	Imported
446	PIPE SPOOL CW03-001(125A)	1	PCS	Imported
447	PIPE SPOOL CW01-001,002,003 (80A)	3	PCS	Imported
448	PIPE SPOOL CW02-001,002,003, 004 (80A)	4	PCS	Imported
449	PIPE SPOOL CW04--001,002,003, 004, 006 (80A)	6	PCS	Imported
450	PIPE SPOOL CW05--001,002 (80A)	2	PCS	Imported
451	PIPE SPOOL LV01-003	1	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
GN. No. 930 (Contd.)*

	(80A)			
452	PIPE SPOOL LV02-003 (80A)	1	PCS	Imported
453	PIPE SPOOL WD02-002, 003 (80A)	2	PCS	Imported
454	PIPE SPOOL WD03-005, 006, 007, 008, 009, 010, 011, 012, 013 (80A)	9	PCS	Imported
455	PIPE SPOOL AV03- 001,002,003 (65A)	3	PCS	Imported
456	PIPE SPOOL CW06- 001,002,003, 004 (65A)	4	PCS	Imported
457	PIPE SPOOL CW07- 001,002,003, 004 (65A)	4	PCS	Imported
458	PIPE SPOOL CW0B- 001,002,003, 004 (65A)	4	PCS	Imported
459	PIPE SPOOL FW05-001 (65A)	1	PCS	Imported
460	PIPE SPOOL LM01- 001,002,003, 004, 005, 006, 007, 008 (65A)	8	PCS	Imported
461	PIPE SPOOL LM02- 001,002,003, 004, 005, 006, 007, 008 (65A)	8	PCS	Imported
462	PIPE SPOOL LV01-001, 002 (65A)	2	PCS	Imported
463	PIPE SPOOL LV02-001, 002 (65A)	2	PCS	Imported
464	PIPE SPOOL WD01-001, 002 (65A)	2	PCS	Imported
465	PIPE SPOOL WD02-001 (65A)	1	PCS	Imported
466	PIPE SPOOL WD03-001, 002, 003 (65A)	3	PCS	Imported
467	PIPE SPOOL AV01-001, 002, 003 (50A)	3	PCS	Imported
468	PIPE SPOOL AV02-001, 002, 003 (50A)	3	PCS	Imported
469	PIPE SPOOL CW09- 001,002,003, 004 (50A)	4	PCS	Imported
470	PIPE SPOOL CW10- 001,002,003 (50A)	3	PCS	Imported
471	PIPE SPOOL CW11- 001,002,003, 004, 005, 006 (50A)	6	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
GN. No. 930 (Contd.)*

472	PIPE SPOOL FT01-001,002,003, 004, 005, 006, 007, 008 (50A)	8	PCS	Imported
473	PIPE SPOOL FW01-001 (50A)	1	PCS	Imported
474	PIPE SPOOL FW06-005 (50A)	1	PCS	Imported
475	PIPE SPOOL LM01-009, 010 (50A)	2	PCS	Imported
476	PIPE SPOOL LM02-009, 010, 011 (50A)	3	PCS	Imported
477	PIPE SPOOL WD01-003 (50A)	1	PCS	Imported
478	PIPE SPOOL WD03-004 (50A)	1	PCS	Imported
479	PIPE SPOOL BG03-009 (40A)	1	PCS	Imported
480	PIPE SPOOL CW01-004, 005, 006 (40A)	3	PCS	Imported
481	PIPE SPOOL CW02-005, 006, 007, 008, 009 (40A)	5	PCS	Imported
482	PIPE SPOOL CW04-007, 008, 009 (40A)	3	PCS	Imported
483	PIPE SPOOL CWO5-003, 004, 005 (40A)	3	PCS	Imported
484	PIPE SPOOL EG01-001, 002, 003, 004(40A)	4	PCS	Imported
485	PIPE SPOOL FGO8-006 (40A)	1	PCS	Imported
486	PIPE SPOOL FM01-001, 002, 003, 004, 005, 006, 007, 010(40A)	8	PCS	Imported
487	PIPE SPOOL FT01-009(40A)	1	PCS	Imported
488	PIPE SPOOL FW01-002, 003, 004, 005(40A)	4	PCS	Imported
489	PIPE SPOOL FW02-001, 002, 003, 004, 005(40A)	5	PCS	Imported
490	PIPE SPOOL FW05-002(40A)	1	PCS	Imported
491	PIPE SPOOL FW06-001, 002, 003, 004(40A)	4	PCS	Imported
492	PIPE SPOOL FM01-008, 009 (32A)	2	PCS	Imported
493	PIPE SPOOL FM02-001, 006 (32A)	2	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
GN. No. 930 (Contd.)*

494	PIPE SPOOL FM03-001, 007 (32A)	2	PCS	Imported
495	PIPE SPOOL FM04-FM04-005, 006, 007, 008, 009, 010, 011, 012, 013, 014, 015, 016, 017 (32A)	13	PCS	Imported
496	PIPE SPOOL BG01-001, 002, 003, 004, 005, 006, 007, 008(25A)	8	PCS	Imported
497	PIPE SPOOL BG02-001, 002, 003, 004, 005, 006, 007, 008(25A)	8	PCS	Imported
498	PIPE SPOOL BG03-001, 002, 003, 004, 005, 006, 007, 008(25A)	8	PCS	Imported
499	PIPE SPOOL BG04-002, 003, 004, 005, 006, 007, 008, 009, 010(25A)	9	PCS	Imported
500	PIPE SPOOL FM02-007, 008 (25A)	2	PCS	Imported
501	PIPE SPOOL FM03-008, 009 (25A)	2	PCS	Imported
502	PIPE SPOOL FM04-001, 002 (25A)	2	PCS	Imported
503	PIPE SPOOL FMOS-001, 002 (25A)	2	PCS	Imported
504	PIPE SPOOL FT01-010 (25A)	1	PCS	Imported
505	PIPE SPOOL FT02-001 (25A)	1	PCS	Imported
506	PIPE SPOOL FW01-006 (25A)	1	PCS	Imported
507	PIPE SPOOL FW03-001, 002, 003(25A)	3	PCS	Imported
508	PIPE SPOOL FW05-003 (25A)	1	PCS	Imported
509	PIPE SPOOL LV03-001, 002, 003, 004, 005, 006, 007, 008, 009, 010, 011, 012, 013 (25A)	13	PCS	Imported
510	PIPE SPOOL LV04-001, 002, 003, 004, 005, 006, 007, 008, 009, 010, 011, 012, ,013, 014 (25A)	14	PCS	Imported
511	PIPE SPOOL LV05-001, 002, 003, 004, 005, 006,	14	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
GN. No. 930 (Contd.)*

	007, 008, 009, 010, 011, 012, 013, 014 (25A)			
512	PIPE SPOOL AC01-001, 002, 003, 004, 005, 008, 009, 010, 011, 012, 013, 018, 019, 020, 023, 027 (25A)	16	PCS	Imported
513	PIPE SPOOL AS04-001, 002, 003, 004, 005, 006, 007 (25A)	7	PCS	Imported
514	PIPE SPOOL AS05-001, 002, 003, 004, 005, 006 (25A)	6	PCS	Imported
515	PIPE SPOOL BG04-001 (20A)	1	PCS	Imported
516	PIPE SPOOL FG01-001, 002, 003, 004, 005, 006, 007, 008, 009, 010 (20A)	10	PCS	Imported
517	PIPE SPOOL FG03-001, 002, 003, 004, 005, 006, 007, 008, 009 (20A)	9	PCS	Imported
518	PIPE SPOOL FG04-001 (20A)	1	PCS	Imported
519	PIPE SPOOL FGOS-001 (20A)	1	PCS	Imported
520	PIPE SPOOL FG05--002, 003 (20A)	2	PCS	Imported
521	PIPE SPOOL FGOS-004, 005, 006, 007, 008(20A)	5	PCS	Imported
522	PIPE SPOOL FM02-002, 003, 004, 005 (20A)	4	PCS	Imported
523	PIPE SPOOL FM03-002, 003, 004, 005, 006 (20A)	5	PCS	Imported
524	PIPE SPOOL FT02-002, 003, 004, 005, 006 (20A)	5	PCS	Imported
525	PIPE SPOOL AS01-001 (20A)	1	PCS	Imported
526	PIPE SPOOL AS02-001, 002 (20A)	2	PCS	Imported
527	PIPE SPOOL ASO5-007, 008, 009, 010, 011 (20A)	5	PCS	Imported
528	PIPE SPOOL DR01-001, 002, 003 (15A)	3	PCS	Imported
529	PIPE SPOOL FG02-001, 002, 003, 004, 005, 006,	11	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
GN. No. 930 (Contd.)*

	007, 008, 009, 010, 011 (15A)			
530	PIPE SPOOL FG04-002, 003, 004, 005, 006, 007, 008, 009 (15A)	8	PCS	Imported
531	PIPE SPOOL FG06- 001,002, 003, 004, 005, 006, 007, 008, 009, 010, 011 (15A)	11	PCS	Imported
532	PIPE SPOOL FG07-001, 002, 003, 004, 005, 006 (15A)	6	PCS	Imported
533	PIPE SPOOL FGO8-001, 002, 003, 004, 005, 007 (15A)	6	PCS	Imported
534	PIPE SPOOL FM02-009, 010, 011, 012 (15A)	4	PCS	Imported
535	PIPE SPOOL FM03-010, 011, 012, 013 (15A)	4	PCS	Imported
536	PIPE SPOOL FM04-003, 004 (15A)	2	PCS	Imported
537	PIPE SPOOL FMOS-003, 004 (15A)	2	PCS	Imported
538	PIPE SPOOL FW03-004, 005, 006, 007, 008 (15A)	5	PCS	Imported
539	PIPE SPOOL FW04-001, 002, 003, 004, 005(15A)	5	PCS	Imported
540	PIPE SPOOL LM01-011, 012, 013, 014, 015, 016, 017, 018, 019 (15A)	9	PCS	Imported
541	PIPE SPOOL LM02-012, 013, 014, 015, 016, 017, 018, 019 (15A)	8	PCS	Imported
542	PIPE SPOOL AC01-006, 007, 014, 015, 016, 017, 021, 022, 024, 025, 026 (15A)	11	PCS	Imported
543	PIPE SPOOL AS03-001 (15A)	1	PCS	Imported
544	PIPE SPOOL AS06-001, 002, 003, 004 (15A)	4	PCS	Imported
545	AIR VENT 5K-40A	6	PCS	Imported
546	AIR VENT 5K-50A	14	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

547	AIR VENT 5K-65A	12	PCS	Imported
548	AIR VENT 5K-100A	2	PCS	Imported
549	SAFETY HELMET	10	PCS	Imported
550	COTTON GLOVES	50	PCS	Imported
551	WORKING CLOTHES	7	PCS	Imported
552	FILE INNER PAPER	100	PCS	Imported
553	PIPE(BILGE_PUMP_SUCTION / 100 A)	1	PCS	Imported
554	PIPE(BILGE_PUMP_DISCHARGE-1 / 80A)	1	PCS	Imported
555	PIPE(BILGE_PUMP_DISCHARGE-2 / 80A)	1	PCS	Imported
556	PIPE(BILGE_PUMP_DISCHARGE-3 / 80A)	1	PCS	Imported
557	PIPE(GS_PUMP_SUCTION / 80A)	1	PCS	Imported
558	PIPE(GS_PUMP_DISCHARGE / 50A)	1	PCS	Imported
559	FLEAT TYPE GLASS LEVEL GAUGE 1360MM	1	PCS	Imported
560	FLEAT TYPE GLASS LEVEL GAUGE 1000MM	1	PCS	Imported
561	FLEAT TYPE GLASS LEVEL GAUGE 1580MM	1	PCS	Imported
562	FLEAT TYPE GLASS LEVEL GAUGE 1640MM	1	PCS	Imported
563	FLEAT TYPE GLASS LEVEL GAUGE 840MM	1	PCS	Imported
564	MACHINE CASE 2600X2100X1300	1	PCS	Imported
565	HALOGEN FLOOD LIGHT PF50H-23UWCFE-BLPAC230V, 500W	2	PCS	Imported
566	HALOGEN SEARCH LIGHT, FIXED TYPE PS1KH-23UWCF-NHALOGEN SEARCH LIGHTAC230V,1KW	2	PCS	Imported
567	RUBBER PACKING 9.5T*50*10	10	PCS	Imported
568	RUBBER PACKING	10	PCS	Imported
569	BRACKET	20	PCS	Imported
570	NUT & WASHER	450	KGS	Imported
571	RANGE HOOD	1	PCS	Imported
572	HATCH COVER	3	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
GN. No. 930 (Contd.)*

573	LIGID LIFERAFT 10 PERSONS	94	pcs	Imported
574	LIFE BUOY WITH SELF IGNITING LIGHT & SELF ACTIVATING SMOKE SIGNAL	2	pcs	Imported
575	LIFE BUOY WITH SELF IGNITING LIGHT	4	pcs	Imported
576	LIFE BUOY WITH 30M LIFE LINE	4	pcs	Imported
577	LIFE BUOY	2	pcs	Imported
578	LIFE JACKET WITH LIGHTING & WHISTLE	1320	pcs	Imported
579	CHILD'S LIFE JACKET WITH LIGHTING & WHISTLE	132	pcs	Imported
580	EMBARKATION LADDER	4	pcs	Imported
581	INFLATABLE LIFERAFT FOR 25 PERSONS (91688778 DAVIT LAUNCHABLE LIFERAFT)	2	pcs	Imported
582	SEMI - PORTABLE FOAM FIRE EXTINGUISHER 45L	1	pcs	Imported
583	FIXED CO2 FIRE-EXTINGUISHING BOTTLE 68L	15	pcs	Imported
584	TOWING LINE Φ 55MM X 180M	1	pcs	Imported
585	MOORING ROPE Φ 40MM X 180M	8	pcs	Imported
586	INSTANT TANKLESS ELECTRIC WATER HEATER	9	pcs	Imported
587	ACCESSORIES FOR INSTANT TANKLESS ELECTRIC WATER HEATER	9	pcs	Imported
588	SOUNDING CAP (PEDAL TYPE) / STPG370#80 50A 600L	8	PCS	Imported
589	SOUNDING CAP (PEDAL TYPE) / STPG370#80 40A 600L	6	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

590	SOUNDING CAP (FLANGE TYPE) / STPG370#80 50A 200L	2	PCS	Imported
591	5K 80A GLOVE CHECK VALVE	2	PCS	Imported
592	5K 80A ANGLE VALVE	1	PCS	Imported
593	5K 50A GLOVE CHECK VALVE	1	PCS	Imported
594	5K 40A GLOVE VALVE	4	PCS	Imported
595	5K 32A GLOVE CHECK VALVE	1	PCS	Imported
596	5K 25A ANGLE EMERGENCY SHUT OFF VALVE	3	PCS	Imported
597	5K 40A ANGLE EMERGENCY SHUT OFF VALVE	1	PCS	Imported
598	5K 125A GLOVE VALVE	1	PCS	Imported
599	5K 80A WATER STRAINER	1	PCS	Imported
600	5K 125A WATER STRAINER	2	PCS	Imported
601	5K 50A FLANGE	2	PCS	Imported
602	5K 125A FLANGE	2	PCS	Imported
603	GASKET 5K 125A	10	PCS	Imported
604	GASKET 5K15	30	PCS	Imported
605	GASKET 5K20	30	PCS	Imported
606	GASKET 5K25	30	PCS	Imported
607	GASKET 5K32	30	PCS	Imported
608	GASKET 5K40	20	PCS	Imported
609	GASKET 5K50	20	PCS	Imported
610	GASKET 5K65	20	PCS	Imported
611	CABLE TIE	500	PCS	Imported
612	SIGNAL LIGHT COLUMN	3	PCS	Imported
613	CABLE TIE (MARKER TIE)	1000	PCS	Imported
614	PROTECTING WELDING LENS	100	PCS	Imported
615	GLOVES	30	PCS	Imported
616	PAINT MARKER	24	PCS	Imported
617	PROTECTIVE GOGGLE	65	PCS	Imported
618	BRUSH	20	PCS	Imported
619	TAPE 19*20	1	PCS	Imported
620	WRENCHES 1.5-10MM	2	PCS	Imported
621	MONKEY SPANNER	3	PCS	Imported
622	WRENCH (SHORT)	1	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

623	JIB	1	PCS	Imported
624	SLEWING BODY AND PEDESTAL	1	PCS	Imported
625	HYDRAULIC OIL CYLINDER	1	PCS	Imported
626	H-P FILTER INSERT	1	PCS	Imported
627	RETURN FILTER INSERT	1	PCS	Imported
628	BITE TYPE FITTINGS	2	PCS	Imported
629	LINE TYPE FITTINGS	2	PCS	Imported
630	OIL CUP	5	PCS	Imported
631	HEX SCREW	6	PCS	Imported
632	WASHER	6	PCS	Imported
633	NUT	4	PCS	Imported
634	PRESSURE AUE	1	PCS	Imported
635	WIRE ROPE	1	PCS	Imported
636	OIL SEAL	1	PCS	Imported
637	FUSE	20	PCS	Imported
638	LAMP	4	PCS	Imported
639	FIXED HOOK UNIT	1	PCS	Imported
640	HEX SCREW	36	PCS	Imported
641	NUT	36	PCS	Imported
642	WASHER	36	PCS	Imported
643	SPRING WASHER	36	PCS	Imported
644	HAND PUMP ROD	1	PCS	Imported
645	BLOCK	2	PCS	Imported
646	ENGINE (MARINE ENGINE)	1	PCS	Imported
647	ENGINE (MARINE ENGINE)	1	PCS	Imported
648	LIFT.TRAVERSE F.E/G/129226-7.0A	8	PCS	Imported
649	BASE PLATE/193170-8.0A	8	PCS	Imported
650	LIFTING TRAVERSE NUT/193169-0.0A	16	PCS	Imported
651	WIRE ROPE/189899-8	4	PCS	Imported
652	SILENCER 1502031850	1	PCS	Imported
653	SILENCER 1502031850	1	PCS	Imported
654	STARTING AIR TANK FOR 6L23/30AK(200LX2)	1	PCS	Imported
655	FLEXIBLE COUPLING(VICTORIA, E19B547)	2	PCS	Imported
656	HEX. SOCKET BOLT(CLASS 8.8)	36	PCS	Imported
657	FLAT WASHER	36	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

658	GAS OUTLET FOR NR20/R	2	PCS	Imported
659	BOLT & NUT	32	PCS	Imported
660	THERMOMETER	2	PCS	Imported
661	EXPANSION JOINT, 300A	2	PCS	Imported
662	EXHAUST TRANSIT PIECE FOR NR20R	1	PCS	Imported
663	GASKET,NR20/R	3	PCS	Imported
664	HEX. BOLT (CLASS 10.9)	32	PCS	Imported
665	SPRING WASHER	32	PCS	Imported
666	HEX.NUT(NORMAL THICKNESS)	32	PCS	Imported
667	EXPANSION JOINT, 400A	2	PCS	Imported
668	GASKET,400A	4	PCS	Imported
669	FLANGE(5K-400A)	4	PCS	Imported
670	HEX. BOLT (CLASS 10.9)	64	PCS	Imported
671	HEX.NUT (M22)	64	PCS	Imported
672	DUPLEX FILTER	2	PCS	Imported
673	PRESS. REGULATING VALVE 1BAR	2	PCS	Imported
674	L.O PRESS REGULATING VALVE	2	PCS	Imported
675	SEA WATER STRAINER	1	PCS	Imported
676	COMP.AIR FILTER	1	PCS	Imported
677	FO S/B PUMP WITH EL-MOTOR FOR 6L23/30,MDO	2	PCS	Imported
678	LO S/B PUMP WITH EL-MOTOR FOR 6L23/30	2	PCS	Imported
679	CJC FINE FILTER, HDU38/100III	2	PCS	Imported
680	MAIN AIR COMPRESSOR	2	PCS	Imported
681	FLEXIBLE HOSE ASSEMBLY FOR AIR OUTLET/0100-2032-01	2	PCS	Imported
682	MAIN AIR COMPRESSOR (ENGINE DRIVEN)	1	PCS	Imported
683	FLEXIBLE HOSE ASSEMBLY FOR AIR OUTLET/0100-2032-01	1	PCS	Imported
684	ENGINE GAS OUTLET	1	PCS	Imported
685	REAMER BOLT,D27M6	8	PCS	Imported
686	STUD BOLT(E/G)	20	PCS	Imported
687	HEX.NUT(NORMAL THICKNESS)	56	PCS	Imported
688	HEX.NUT(THIN	56	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

	THICKNESS)			
689	WASHER,PLAIN	28	PCS	Imported
690	CHOCK LINER F.E/G REAMER	8	PCS	Imported
691	CHOCK LINER FOR STUD	20	PCS	Imported
692	JACKING SCREW,M24	8	PCS	Imported
693	COLLISION CHOCK(E/G)	16	PCS	Imported
694	REAMER BOLTS FOR G/B FOUNDATION	8	PCS	Imported
695	SETTING BOLTS FOR G/B FOUNDATION	8	PCS	Imported
696	JACKING BOLT FOR G/B FOUNDATION	8	PCS	Imported
697	NUTS	32	PCS	Imported
698	COLLISION CHOCK(GEAR BOX)	8	PCS	Imported
699	ENG. & PROP. CTRL CABINET	1	PCS	Imported
700	ENG. & PROP. CTRL CABINET	1	PCS	Imported
701	GROUP STARTER (6P, DOL, 1 PWR, W/ RPB, HTR)	1	PCS	Imported
702	AIR SOURCE PANEL	1	PCS	Imported
703	PROPELLER SHAFT IND. SYSTEM	2	PCS	Imported
704	E/P CONVERTER W.PRESS GAUGE	2	PCS	Imported
705	CHECK CHOKE VALVE (GR-1/4, PN 2101)	2	PCS	Imported
706	CYLINDER LINER (STEP RING)/ 11610-03-1	1	PCS	Imported
707	CYLINDER HEAD MODULE/1501014230	1	PCS	Imported
708	CON-ROD ASSY WITH BUSH/11612-01-1	1	PCS	Imported
709	STEPPED PISTON FOR FLAME RING/ 11614-09-1	1	PCS	Imported
710	MAIN BEARING/11012- 01-03	1	PCS	Imported
711	STUD, MAIN B/R CAP/11012-01-04	2	PCS	Imported
712	NUT /11012-01-05	2	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

713	LOCK PIECE/11012-01-06	1	PCS	Imported
714	SCREW/11012-01-08	1	PCS	Imported
715	HEX.SOCKET BOLT/11012-01-09	6	PCS	Imported
716	DISTANCE PIECE/11012- 01-10	2	PCS	Imported
717	BRACING BOLT/11012- 01-11	2	PCS	Imported
718	THRUST WASHER(1630275-4)/ 11012-01-13	2	PCS	Imported
719	LOCKING PIECE/11012- 01-14	4	PCS	Imported
720	HEX.SOCKET BOLT/11012-01-15	4	PCS	Imported
721	RUBBER RING/ 11610-03-3-CYLINDER LINER	2	PCS	Imported
722	SEALING RING (T=0.5)/11610-03-4	1	PCS	Imported
723	FLAME RING F.CYL/11610-03-5	1	PCS	Imported
724	STUD CYL COVER/11012- 01-24	2	PCS	Imported
725	NUT/11012-01-29	2	PCS	Imported
726	EXHAUST VALVE/11616- 01-H6	6	PCS	Imported
727	ROTO-CAP ASS'Y/116-01- H14	6	PCS	Imported
728	CONICAL RING/11616-01- H13	6	PCS	Imported
729	SPRING- EXTERNAL/11616-01-H12	6	PCS	Imported
730	SPRING- INTERNAL/11616-01-H11	6	PCS	Imported
731	INDICATOR VALVE/11618-02-10	1	PCS	Imported
732	CONNECT. PLECE/11618- 02-40	1	PCS	Imported
733	GASKET(COPPER)/11618- 02-30	2	PCS	Imported
734	GASKET(COPPER) 1.0MM/11618-02-20	2	PCS	Imported
735	GASKET(COPPER) 0.8MM/11618-02-20	2	PCS	Imported
736	FUEL INJECTION	6	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
GN. No. 930 (Contd.)*

	VALVE/12018-02-20			
737	CON ROD BEARING(1600133-9.3)/ 11612-01-10	1	PCS	Imported
738	PISTON PIN/11614-09-3	1	PCS	Imported
739	RETAINING RING F BORING/11614-09-6	2	PCS	Imported
740	PISTON RING/11614-09- A1	1	PCS	Imported
741	PISTON RING/11614-09- A2	1	PCS	Imported
742	PISTON RING/11614-09- A3	1	PCS	Imported
743	OIL SCRAPER RING/11614-09-A4	1	PCS	Imported
744	FUEL INJ PUMP(L'ORANGE, PYO- A073C)/ 12016-01	1	PCS	Imported
745	FUEL INJ. PIPE/120220- 01S	1	PCS	Imported
746	O-RING FOR INSERT FOR FUEL V/V/ 11616-01-B4	1	PCS	Imported
747	O-RING FOR COOLING JACKET / 11616-01-F34	2	PCS	Imported
748	O-RING VALVE SEAT RING /11616-01-B10	4	PCS	Imported
749	O-RING FOR SLEEVE F. C/W /11616-01-K3	8	PCS	Imported
750	O-RING FOR V/V GUIDE /11616-01-22	4	PCS	Imported
751	RUBBER RING/11610-03-3	2	PCS	Imported
752	FILTER ELEMENT FOR L.O FILTER /186416-4	4	PCS	Imported
753	FILTER ELEMENT FOR F.O FILTER /186417-2.1A	2	PCS	Imported
754	SPARE BOX/Y910148300ZA	2	PCS	Imported
755	AIR FILTER MAT FOR T/C/84140047-2M	4	PCS	Imported
756	FILTER ELEMENT FOR L.O FILTER/	8	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
GN. No. 930 (Contd.)*

	186416-4			
757	FILTER ELEMENT FOR F.O FILTER/ 186417-2.1A	4	PCS	Imported
758	MATAL BEARING/370.1- F.O. PUMP	6	PCS	Imported
759	MATAL BEARING/370.2- F.O. PUMP	2	PCS	Imported
760	MOTOR BALL BEARING/ 6204ZZC3-F.O. PUMP	2	PCS	Imported
761	MOTOR BALL BEARING/ 6203ZZC3-F.O. PUMP	2	PCS	Imported
762	MECHANICAL SEAL/433.1-F.O. PUMP	2	PCS	Imported
763	SAFETY VALVE SPRING/765.1-F.O. PUMP	2	PCS	Imported
764	RING-F.O. PUMP	8	PCS	Imported
765	COUPLING BOLT-F.O. PUMP	8	PCS	Imported
766	COUPLING BUSH-F.O. PUMP	8	PCS	Imported
767	NUT-F.O. PUMP	8	PCS	Imported
768	MATAL BEARING/370.1- L.O. PUMP	6	PCS	Imported
769	MATAL BEARING/370.2- L.O. PUMP	2	PCS	Imported
770	MOTOR BALL BEARING/ 6204ZZC3-L.O. PUMP	2	PCS	Imported
771	MOTOR BALL BEARING/ 6203ZZC3-L.O. PUMP	2	PCS	Imported
772	MECHANICAL SEAL/433.1-L.O. PUMP	2	PCS	Imported
773	SAFETY VALVE SPRING/765.1-L.O. PUMP	2	PCS	Imported
774	RING-L.O. PUMP	12	PCS	Imported
775	COUPLING BOLT-L.O. PUMP	12	PCS	Imported
776	COUPLING BUSH-L.O. PUMP	12	PCS	Imported
777	NUT-L.O. PUMP	12	PCS	Imported
778	PISTON RING (RECTANGULAR)/ 3806-1067-00	2	PCS	Imported
779	PISTON RING (UNDER CUT)/ 3807-1067-00	2	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

780	OIL SRAPING RING / 3808-1052-00	4	PCS	Imported
781	PISTIN RING (RECTANGULAR)/ 3806-1056-00	6	PCS	Imported
782	PISTON RING (UNDER CUT)/ 3807-1056-00	2	PCS	Imported
783	OIL SCRAPING RING/ 3808-1042-00	2	PCS	Imported
784	GASKET RING/ 2110-1102-00	2	PCS	Imported
785	GASKET RING/ 2110-1202-00	2	PCS	Imported
786	PACKING, CYLINDER HEAD/ 2110-1103-00	2	PCS	Imported
787	PACKING, CYLINDER HEAD/ 2110-1203-00	2	PCS	Imported
788	AIR FILTER ELEMENT/ 3110-8810-02	2	PCS	Imported
789	CONCENTRIC VALVE ASSEMBLY/ 0110-7100-00	2	PCS	Imported
790	CONCENTRIC VALVE ASSEMBLY/ 0220-7200-00	2	PCS	Imported
791	PRESSURE GAUGE/ 3603-8005-00	4	PCS	Imported
792	PRESSURE GAUGE/ 3603-8008-00	4	PCS	Imported
793	PISTON RING (RECTANGULAR)/ 806-1067-00-3,000HOURS	2	PCS	Imported
794	PISTON RING (UNDER CUT)/ 3807-1067-00-3,000HOURS	2	PCS	Imported
795	OIL SRAPING RING/ 3808-1052-00-3,000HOURS	4	PCS	Imported
796	PISTIN RING (RECTANGULAR)/ 3806-1056-00-3,000HOURS	6	PCS	Imported
797	PISTON RING (UNDER CUT)/ 3807-1056-00-3,000HOURS	2	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

798	OIL SCRAPING RING / 3808-1042-00-3,000HOURS	2	PCS	Imported
799	GASKET RING/ 2110-1102-00-3,000HOURS	6	PCS	Imported
800	GASKET RING/ 2110-1202-00-3,000HOURS	6	PCS	Imported
801	PACKING, CYLINDER HEAD/ 2110-1103-00-3,000HOURS	6	PCS	Imported
802	PACKING, CYLINDER HEAD/ 2110-1203-00-3,000HOURS	6	PCS	Imported
803	AIR FILTER ELEMENT/ 3110-8810-02-3,000HOURS	6	PCS	Imported
804	CONCENTRIC VALVE ASSEMBLY/ 0110-7100-00-3,000HOURS	2	PCS	Imported
805	CONCENTRIC VALVE ASSEMBLY/ 0220-7200-00-3,000HOURS	2	PCS	Imported
806	FLEXIBLE HOSE ASSEMBLY/ 0100-2033-03-LT-115/LT- 116	2	PCS	Imported
807	SPARE PART BOX/ 19-3301-0100-LT-115/LT- 116	2	PCS	Imported
808	PISTON RING (RECTANGULAR)/X 3806-1066-00	2	PCS	Imported
809	PISTON RING (UNDER CUT)/ 3807-1066-00	2	PCS	Imported
810	OIL SCRAPING RING / 3808-1051-00	4	PCS	Imported
811	PISTIN RING (RECTANGULAR)/ 3806-1054-00	8	PCS	Imported
812	OIL SCRAPING RING / 3808-1040-00	2	PCS	Imported
813	GASKET RING/ 2110-1102-00-LT-105/LT- 106	2	PCS	Imported
814	GASKET RING/ 2110-1202-00-LT-105/LT- 106	2	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
GN. No. 930 (Contd.)*

815	PACKING, CYLINDER HEAD/ 2110-1103-00-LT-105/LT-106	2	PCS	Imported
816	PACKING, CYLINDER HEAD/ 2110-1203-00-LT-105/LT-106	2	PCS	Imported
817	AIR FILTER ELEMENT/ 3110-8810-02-LT-105/LT-106	2	PCS	Imported
818	CONCENTRIC VALVE ASSEMBLY/ 0110-7100-00-LT-105/LT-106	2	PCS	Imported
819	CONCENTRIC VALVE ASSEMBLY/ 0220-7200-00-LT-105/LT-106	2	PCS	Imported
820	PRESSURE GAUGE/ 3603-8008-00-LT-105/LT-106	4	PCS	Imported
821	SCREW DRIVER/ 19-0031-2031	2	PCS	Imported
822	PLIERS/19-0031-2032	2	PCS	Imported
823	BOX SPANNER/19-0031-2033	2	PCS	Imported
824	SPANNER DOUBLE DNDER/19-0031-2034	2	PCS	Imported
825	SPANNER DOUBLE DNDER/19-0031-2035	2	PCS	Imported
826	SPANNER DOUBLE DNDER/19-0031-2036	2	PCS	Imported
827	PISTON RING (RECTANGULAR)/ 3806-1066-00-LT-104E/LT-105E/LT-106E	2	PCS	Imported
828	PISTON RING (UNDER CUT)/ 3807-1066-00-LT-104E/LT-105E/LT-106E	2	PCS	Imported
829	OIL SCRAPING RING / 3808-1051-00-LT-104E/LT-105E/LT-106E	4	PCS	Imported
830	PISTIN RING (RECTANGULAR)/	8	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

	3806-1054-00-LT-104E/LT-105E/LT-106E			
831	OIL SCRAPING RING / 3808-1040-00-LT-104E/LT-105E/LT-106E	2	PCS	Imported
832	GASKET RING/ 2110-1102-00-LT-104E/LT-105E/LT-106E	6	PCS	Imported
833	GASKET RING/ 2110-1202-00-LT-104E/LT-105E/LT-106E	6	PCS	Imported
834	PACKING, CYLINDER HEAD/ 2110-1103-00-LT-104E/LT-105E/LT-106E	6	PCS	Imported
835	PACKING, CYLINDER HEAD/ 2110-1203-00-LT-104E/LT-105E/LT-106E	6	PCS	Imported
836	AIR FILTER ELEMENT/ 3110-8810-02-LT-104E/LT-105E/LT-106E	6	PCS	Imported
837	CONCENTRIC VALVE ASSEMBLY/ 0110-7100-00-LT-104E/LT-105E/LT-106E	2	PCS	Imported
838	CONCENTRIC VALVE ASSEMBLY/ 0220-7200-00-LT-104E/LT-105E/LT-106E	2	PCS	Imported
839	M.C.B /1C6ON 2P 10A	2	PCS	Imported
840	M.C.B /1C6ON 2P 2A	2	PCS	Imported
841	M.C.B /1C6ON 2P 6A	2	PCS	Imported
842	M.C.B /1C6ON 2P 4A	2	PCS	Imported
843	LAMP REMOVER/02-906	2	PCS	Imported
844	LENS REMOVER/02-905	2	PCS	Imported
845	RELAY/G2R-1-SND	6	PCS	Imported
846	RELAY/788-312	24	PCS	Imported
847	L.E.D /YSBRL34-DL24W	4	PCS	Imported
848	L.E.D /YSBRL34-DL24Y	2	PCS	Imported
849	L.E.D /YSBRL34-DL24G	2	PCS	Imported
850	L.E.D /YSBRL34-DL24R	2	PCS	Imported
851	DIODE/1N5408	4	PCS	Imported
852	RESISTOR/10KOHM,1/2W	4	PCS	Imported
853	LAMP BULB /10- 1313.1209	208	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

854	SPARE PARTS BOX	2	PCS	Imported
855	MAGNETIC CONTACTOR / HGC-12	2	PCS	Imported
856	MAGNETIC CONTACTOR / HGC-32	2	PCS	Imported
857	LAMP XB5AVB/WHITE(1)	2	PCS	Imported
858	LAMP XB5AVB/RED(4)	2	PCS	Imported
859	LAMP XB5AVM/ORANGE(5)	2	PCS	Imported
860	FUSE SB-C1/1A	72	PCS	Imported
861	PUSH BUTTON LAMP/ XB5-AW33B5(GREEN LED)	2	PCS	Imported
862	PUSH BUTTON /XB5-AA42(RED COLOR)	2	PCS	Imported
863	CONTROL RELAY/MY4N(220VAC)	2	PCS	Imported
864	TIMER RELAY/H3YN-2(220VAC)	2	PCS	Imported
865	GASKET/DHFAC-L23-A1	2	PCS	Imported
866	GASKET	2	PCS	Imported
867	PROTECTING ANODE/DHFAC-L23-A1	12	PCS	Imported
868	WOOD PLUG	20	PCS	Imported
869	NYLON BRUSH/1, L=710	2	PCS	Imported
870	NYLON BRUSH/1, L=150	2	PCS	Imported
871	HANDLE	2	PCS	Imported
872	BAR	2	PCS	Imported
873	JOINT	4	PCS	Imported
874	SPARE BOX - AIR TANK	2	PCS	Imported
875	GASKET - AIR TANK	8	PCS	Imported
876	SPRING - AIR TANK	4	PCS	Imported
877	O-RING FOR INLET CASING/11816-01-58	12	PCS	Imported
878	O-RING FOR COOLING WATER JACKET/ 11616-01-F34	24	PCS	Imported
879	GASKET FOR INTERMEDIATE PIECE/ 11818-03-A5	24	PCS	Imported
880	O-RING FOR INSERT FOR FUEL VALVE/ 11616-01-B4	12	PCS	Imported
881	O-RING FOR C.W NIPPLE/11616-01-K3	12	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

882	O-RING FOR PUSH ROD PIPE/11414-03-18	48	PCS	Imported
883	GASKET FOR ROLLER GUIDE TOP COVER/ 1000519-2.1B	24	PCS	Imported
884	GASKET/11812-01-2	2	PCS	Imported
885	GASKET/11812-01-5	2	PCS	Imported
886	O-RING FOR FUEL VALVE/12018-02-11	144	PCS	Imported
887	O-RING/704891-1	72	PCS	Imported
888	SEALING RING/12020- 01S-16	72	PCS	Imported
889	O-RING FOR HIGH PRESSURE PIPE/ 12020-01-17	72	PCS	Imported
890	INJECTION NOZZLE/12018-02-3	12	PCS	Imported
891	PISTON RING/11614-09- A1-12,000HR	12	PCS	Imported
892	PISTON RING/11614-09- A2-12,000HR	12	PCS	Imported
893	PISTON RING/11614-09- A3-12,000HR	12	PCS	Imported
894	SCRAPER RING/11614-09- A4	12	PCS	Imported
895	SPRING WASHER CAMSHAFT BOLT/ 11410-02-17	12	PCS	Imported
896	O-RING FOR CAMSHAFT COVER / 11014-02-2	2	PCS	Imported
897	LUBRICANT OILFILTER CARTRIDGE/ 12816-01-11	32	PCS	Imported
898	GASKET FOR TOP SHIELD/11620-02-A10	84	PCS	Imported
899	GASKET FOR TOP SHIELD/11620-02-A9	84	PCS	Imported
900	SEAL FOR RELIEF VALVE/1502012780	16	PCS	Imported
901	O-RING FOR CRANKCASE DOORS/ 11014-04-A5	16	PCS	Imported
902	SEAL FOR RELIEF VALVE/1502012780	8	PCS	Imported
903	PACKING/12812-01-14	6	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
GN. No. 930 (Contd.)*

904	BUSH FOR LUB.OIL PUMP/12812-01-5	10	PCS	Imported
905	GASKET/12812-01-22	2	PCS	Imported
906	TURBINE NOZZLE RING FOR T/C/513.001	2	PCS	Imported
907	SPARE BOX/Y910148300ZA-12,000HR	2	PCS	Imported
908	THERMOMETER, 100°C/P133C2108100	2	PCS	Imported
909	THERMOMETER, 250°C/9002008700	2	PCS	Imported
910	THERMOMETER/9001004 810-1	12	PCS	Imported
911	THERMOMETER/9001004 810-3	14	PCS	Imported
912	THERMOMETER, 100°C/P133A2207100	12	PCS	Imported
913	PRESSURE GAUGE/1502036270-5	2	PCS	Imported
914	PRESSURE GAUGE/1502036270-3	2	PCS	Imported
915	PRESSURE GAUGE/1502036270-2	2	PCS	Imported
916	PRESSURE GAUGE/1502009930-7	4	PCS	Imported
917	PRESSURE GAUGE/1502036270-4	2	PCS	Imported
918	PRESS S/W, 0-10BAR/ 1131-P141D0060210	2	PCS	Imported
919	TRANSMITTER. 0-6BAR/ 1131-P810A0402100	4	PCS	Imported
920	DIFF P S/W/P141E0030210	2	PCS	Imported
921	TEMP. SENSOR L=150/9002003990	2	PCS	Imported
922	LEVEL SENSOR F. ENG' OIL/167221-9.0D	2	PCS	Imported
923	DIFF PRESSURE S/W/ 1131-P141E0020210	2	PCS	Imported
924	TRANSMITTER. 0-16K/ 1131-P810A0602100	2	PCS	Imported
925	PRESSURE S/W, 1-10K/P141C032010	2	PCS	Imported
926	LEVEL ALARM FOR FUEL OIL LEAKAGE/ 2055078-4.1A	2	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
GN. No. 930 (Contd.)*

927	TEMP SENSOR FOR EXH. GAS OUT LET/ 1602008820	12	PCS	Imported
928	PRESS.S/W, 0-4BAR / 1131-P141D0040210	2	PCS	Imported
929	THERMO S/W 20- 150/P143E1201005	2	PCS	Imported
930	TEMP.SENSOR/900200401 0	2	PCS	Imported
931	TRANSMITTER. 0-6BAR/ 1131-P810A0402100	2	PCS	Imported
932	PRESS S/W 4- 40BAR/P141D0090210	2	PCS	Imported
933	PRESS S/W 0-10BAR/ 1131-P141D0060210	2	PCS	Imported
934	TEMP.SENSOR L=60/9002004030	2	PCS	Imported
935	SPARE BOX/Y910148300ZA	1	PCS	Imported
936	F.W.PUMP CLOCKWISE ROTA/ 13010-01-1-C.W	1	PCS	Imported
937	LOCK WHSHER/ 13010-01-5 - H.T. PUMP C.W.	1	PCS	Imported
938	NUT/13210-01-4 - H.T. PUMP C.W.	1	PCS	Imported
939	SQUARE BRIGHT DRAWN KEY STEEL/ 13010-01-3	1	PCS	Imported
940	GEAR WHEEL FOR PUMP DRIVING/ 13010-01-2	1	PCS	Imported
941	HEX.SOCKET BOLT/ 13010-01-60 - H.T. PUMP C.W.	8	PCS	Imported
942	CYL.PIN/13010-01-70 - H.T. PUMP C.W.	2	PCS	Imported
943	S/W PUMP,CLOCKWISE ROTATI/ 13010-01-1-C.W	1	PCS	Imported
944	LOCK WHSHER/ 13210-01-13(R29H25) - L.T. PUMP C.W.	1	PCS	Imported
945	NUT/13210-01-4 - L.T. PUMP C.W.	1	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
GN. No. 930 (Contd.)*

946	SQUARE BRIGHT - DRAWN KEY STEEL/ 13210-01-3	1	PCS	Imported
947	GEAR WHEEL FOR PUMP DRIVING/ 13010-01-2	1	PCS	Imported
948	HEX.SOCKET BOLT/ 13210-01-60 - L.T. PUMP C.W.	8	PCS	Imported
949	CYL.PIN/13210-01-70 - L.T. PUMP C.W.	2	PCS	Imported
950	FRESH WATER PUMP, ANTI C.W/ 13010-01-1-C.C.W	1	PCS	Imported
951	LOCK WASHER/ 13010-01-5 - H.T. PUMP C.C.W	1	PCS	Imported
952	NUT/13210-01-4 - H.T. PUMP C.C.W.	1	PCS	Imported
953	SQUARE BRIGHT - DRAWN KEY STEEL/ 13010-01-3	1	PCS	Imported
954	GEAR WHEEL FOR PUMP DRIVING/ 13010-01-2	1	PCS	Imported
955	HEX.SOCKET BOLT/ 13010-01-60 - H.T. PUMP C.C.W.	8	PCS	Imported
956	CYL.PIN/13010-01-70 - H.T. PUMP C.C.W.	2	PCS	Imported
957	SEAWATER PUMP,ANT C.W/ 13210-01-1-C.C.W	1	PCS	Imported
958	LOCK WHSHER/ 13210-01-13 - L.T. PUMP C.C.W.	1	PCS	Imported
959	NUT/13210-01-4 - L.T. PUMP C.C.W.	1	PCS	Imported
960	SQUARE BRIGHT DRAWN KEY STEEL/ 13210-01-3	1	PCS	Imported
961	GEAR WHEEL FOR PUMP DRIVING/ 13010-01-2	1	PCS	Imported
962	HEX. SOCKET BOLT/ 13210-01-60 - L.T. PUMP	8	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

	C.C.W.			
963	CYL.PIN/13210-01-70 - L.T. PUMP C.C.W.	2	PCS	Imported
964	HYD'TOOL BOX FOR CYL' HEAD/ 19012-03-10	1	PCS	Imported
965	HYD' HAND PUMP(MAX. 1500BAR)/ 19012-03-A5,A6	1	PCS	Imported
966	HIGH PRESSURE HOSE/19012-03-E2	4	PCS	Imported
967	HIGH PRESSURT HOSE/19012-03-E3	1	PCS	Imported
968	DISTRIBUTOR BLOCK FOR CYL. HEAD/ 19012-03-F1	1	PCS	Imported
969	DISTRUIUTOR BLOCK FOR MAIN BEARING CAP/19012-03-E1	1	PCS	Imported
970	HYD'TOOL BOX FOR MAIN BEARING CAP/ 19012-03-3	1	PCS	Imported
971	WIRE STRAP(MAX, LOAD 600KG)/ 19012-03-5	1	PCS	Imported
972	EYE BOLT/19012-03-6	1	PCS	Imported
973	GUIDE PIPE F. MAIN BEARING CAP/ 19012-03-7	2	PCS	Imported
974	TOOL F. REMOV.MAIN BRG/19012-03-8	1	PCS	Imported
975	SPECIAL WRENCH F. MAIN BRG/ 19012-03-9	1	PCS	Imported
976	CRANKSHAFT DEFLECTION GAUGE/ 19012-03-58	1	PCS	Imported
977	TURNING BAR/19012-03- 1	1	PCS	Imported
978	DOUBLE END SPANNER/19012-03-11	1	PCS	Imported
979	BOX WITH GRINDING RING/19012-03-12	1	PCS	Imported
980	LIFTING TOOL FOR CYL. HEAD/ 1902-03-13	1	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

981	HONESTONE/19012-03-14	1	PCS	Imported
982	LIFTING TOOL FOR CYL. LINER/ 19012-03-15	1	PCS	Imported
983	WASTE OIL TRAY/19012- 03-16	1	PCS	Imported
984	RETAINING TOOL FOR CYL.LINER/ 19012-03-17	1	PCS	Imported
985	EYE BOLT/19012-03-18	1	PCS	Imported
986	PLIER FOR SECUR RINGS FOR BORING/ 19012-03-19	1	PCS	Imported
987	PISTON RING EXPANDER/19012-03-20	1	PCS	Imported
988	GUIDE RING FOR MOUNTING OF PISTON/ 19012-03-21	1	PCS	Imported
989	FEELER GAUGE SET/19012-03-22	2	PCS	Imported
990	MOUNTING TOOL FOR VALVE/19012-03-23	1	PCS	Imported
991	EXTRACTOR FOR FUEL INJECTION V/V/ 19012-03-31	1	PCS	Imported
992	PLIER FOR SECUR RING FOR BORING/ 19012-03-37	1	PCS	Imported
993	SPANNER FOR FUEL INJ PUMP/ 19012-03-36	1	PCS	Imported
994	WRENCH WITH SQUARE HOLE/ 19012-03-32	1	PCS	Imported
995	PIN WRENCH FOR HIGH- PRESSURE FUEL/ 19012-03-25	1	PCS	Imported
996	GRINDING TOOL FOR FUEL V/V SEAT/ 19012-03-33	1	PCS	Imported
997	GRIND RING FOR UNION NUT SEAT/ 19012-03-34	1	PCS	Imported
998	SOCKET SPANNER FOR FUEL INJECTION V/V/19012-03-35	1	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

999	TOMMY BAR/19012-03-38	1	PCS	Imported
1000	COMBINATION SPANNER/19012-03-39	1	PCS	Imported
1001	HALF MOON RING SPANNER/19012-03-40	1	PCS	Imported
1002	SPANNER FOR INTERMEDIATE PIECE/ 19012-03-41	1	PCS	Imported
1003	WRENCH FOR EXHAUST INTER PIECE/ 19012-03-42	1	PCS	Imported
1004	TORQUE WRENCH(25-150NM)/ 19012-03-43	1	PCS	Imported
1005	TORQUE WRENCH(70-350NM)/ 19012-03-44	1	PCS	Imported
1006	REDUCER 3/4" TO 1/2"/19012-03-45	1	PCS	Imported
1007	EXTENSION BAR/19012-03-46	1	PCS	Imported
1008	RATCHER/(1626480-6)	1	PCS	Imported
1009	TEE HANDLE SQUARE DRIVE/19012-03-47	1	PCS	Imported
1010	SOCKET SPANNER /19012-03-48	1	PCS	Imported
1011	SOCKET SPANNER/19012-03-49	1	PCS	Imported
1012	SOCKET WRENCH/19012-03-50	1	PCS	Imported
1013	CONVERTER 1/2" TO 3/4"/19012-03-51	1	PCS	Imported
1014	SOCKET SPANNER/19012-03-52	1	PCS	Imported
1015	SOCKET SPANNER/19012-03-53	1	PCS	Imported
1016	EYE BOLT/19012-03-55	1	PCS	Imported
1017	EYE BOLT/19012-03-56	1	PCS	Imported
1018	HEX.BOLT/P000E0020120	2	PCS	Imported
1019	SINGLE SPANNER/19010-01-9	1	PCS	Imported
1020	SINGLE SPANNER/19010-01-8	1	PCS	Imported
1021	SINGLE SPANNER/19010-01-7	1	PCS	Imported
1022	SINGLE SPANNER/19010-	1	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

	01-6			
1023	SINGLE SPANNER/19010-01-5	1	PCS	Imported
1024	SINGLE SPANNER/19010-01-4	1	PCS	Imported
1025	SINGLE SPANNER/19010-01-3	1	PCS	Imported
1026	SINGLE SPANNER/19010-01-2	1	PCS	Imported
1027	SINGLE SPANNER/19010-01-1	1	PCS	Imported
1028	KEY HEXAGON SOCKET/19010-01-10	1	PCS	Imported
1029	KEY HEXAGON SOCKET/19010-01-11	1	PCS	Imported
1030	KEY HEXAGON SOCKET/19010-01-12	1	PCS	Imported
1031	KEY HEXAGON SOCKET/19010-01-13	1	PCS	Imported
1032	KEY HEXAGON SOCKET/19010-01-14	1	PCS	Imported
1033	KEY HEXAGON SOCKET/19010-01-15	1	PCS	Imported
1034	KEY HEXAGON SOCKET/19010-01-16	1	PCS	Imported
1035	KEY HEXAGON SOCKET/19010-01-17	1	PCS	Imported
1036	KEY HEXAGON SOCKET/19010-01-18	1	PCS	Imported
1037	KEY HEXAGON SOCKET/19010-01-19	1	PCS	Imported
1038	KEY HEXAGON SOCKET/19010-01-20	1	PCS	Imported
1039	NOZZLE TEST PUMP/19012-03-26	1	PCS	Imported
1040	HOLDER FOR CLEANING NEEDLE/ 19012-03-29	1	PCS	Imported
1041	MEASURING DEVICE FOR CAMTIMING/ (150101258B)	1	PCS	Imported
1042	HAND GRINDING TOOL/19012-03-24	1	PCS	Imported
1043	P-MAX INDICATOR/(1131-83200173-2)	1	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
GN. No. 930 (Contd.)*

1044	CYL.BORE GAUGE/(34000411A-23)	1	PCS	Imported
1045	T/C MOUNTING COVER, EMERGENCY/ (11.59686-0033-1)	1	PCS	Imported
1046	TOOL AND SPARE BOX/19012-03-36A	2	PCS	Imported
1047	TRIGGER FOR THRUST PIN/19012-03-36A	1	PCS	Imported
1048	HANDWHEEL FOR INDICATOR VALVE/ 11618-02-50	1	PCS	Imported
1049	CABLE 0.6/1KV TPYCYSLA -1.5X3C	200	METER	Imported
1050	CABLE 250V MPYCSLA 7CX1.0	60	METER	Imported
1051	CABLE 250V TTYCY 1P X 0.75	60	METER	Imported
1052	CABLE RG12UY	200	METER	Imported
1053	CABLE 250V MPYCY 7CX1.0	120	METER	Imported
1054	CABLE 250V MPYCYSLA 4CX1.0	60	METER	Imported
1055	CABLE 250V MPYCSLA 4CX1.0	40	METER	Imported
1056	CABLE DPYC 1.5X2C	200	METER	Imported
1057	CABLE 5C-2V	800	METER	Imported
1058	CABLE 250V TTYC 1PX0.75	500	METER	Imported
1059	CABLE 250V TTYCSLA 1P X 0.75	150	METER	Imported
1060	CABLE 250V MPYCYSLA 7CX 1.0	400	METER	Imported
1061	CABLE DPYCY 1.5 X 2C	700	METER	Imported
1062	CABLE TPYCY 1.5 X 3C	600	METER	Imported
1063	CABLE 150/250V TTYCSLA	900	METER	Imported
1064	EMERGENCY LIGHT IP20-24BNEG 20W, 24V	58	PCS	Imported
1065	KVM POWDER	10	PCS	Imported
1066	CABLE TIE 140MM	15	PCS	Imported
1067	CABLE TIE 300MM	40	PCS	Imported
1068	CABLE TIE 450MM	10	PCS	Imported
1069	LUG TERMINAL 6	30	PCS	Imported
1070	LUG TERMINAL 10	30	PCS	Imported
1071	LUG TERMINAL 16	30	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

1072	LUG TERMINAL 35	20	PCS	Imported
1073	LUG TERMINAL 50	20	PCS	Imported
1074	LUG TERMINAL 70	20	PCS	Imported
1075	TERMINAL CAP 6SQ	3000	PCS	Imported
1076	TERMINAL CAP10SQ	1500	PCS	Imported
1077	TERMINAL CAP 16SQ	1500	PCS	Imported
1078	TERMINAL CAP 35SQ	1200	PCS	Imported
1079	TERMINAL CAP 50SQ	900	PCS	Imported
1080	TERMINAL CAP 70SQ	300	PCS	Imported
1081	TAPE 19MM18Y	40	PCS	Imported
1082	TAPE(RED)	10	PCS	Imported
1083	TAPE(WHITE)	10	PCS	Imported
1084	LABEL CASSETTE	1	PCS	Imported
1085	ELECTRONIC TUBE	1	PCS	Imported
1086	TCT HOLE SAW(DH-412) 041 MM FOR GEAR BOX TERMINAL BOX	1	PCS	Imported
1087	TCT HOLE SAW(DH-412) 021 MM FOR GEAR BOX TERMINAL BOX	1	PCS	Imported
1088	CABLE GLAND(BIG) FOR GEAR BOX TERMINAL BOX	2	PCS	Imported
1089	CABLE GLAND(SMALL) FOR GEAR BOX TERMINAL BOX	3	PCS	Imported
1090	U-BOLT SS41 10X15A	30	PCS	Imported
1091	U-BOLT SS41 10X20A	30	PCS	Imported
1092	U-BOLT SS41 10X25A	30	PCS	Imported
1093	U-BOLT SS41 10X32A	30	PCS	Imported
1094	U-BOLT SS41 10X40A	100	PCS	Imported
1095	U-BOLT SS41 10X50A	30	PCS	Imported
1096	U-BOLT SS41 10X65A	30	PCS	Imported
1097	HEX NUT SS41 10	1200	PCS	Imported
1098	HEX NUT SS41 12	200	PCS	Imported
1099	PLAIN WASHER SS41 10	1200	PCS	Imported
1100	PLAIN WASHER SS41 12	200	PCS	Imported
1101	MOUNT 30MM WHITE	500	PCS	Imported
1102	MOUNT 30MM BLACK	500	PCS	Imported
1103	ELBOW, LONG 45° 40A	10	PCS	Imported
1104	ELBOW, LONG 45° 32A	10	PCS	Imported
1105	ELBOW, LONG 45° 25A	10	PCS	Imported
1106	ELOBOW, LONG 90 °40A	30	PCS	Imported
1107	ELOBOW, LONG 90 °32A	30	PCS	Imported
1108	ELOBOW, LONG 90 °25A	30	PCS	Imported

*Value Added Tax (Exemption) (Rehabilitation of Mv Victoria at Mwanza Branch)
(M/S Ktmi Co. Ltd in Joint Venture With Yuko's Enterprises E.A Ltd) Amendment
Gn. No. 930 (Contd.)*

1109	ELOBOW, LONG 90 °20A	20	PCS	Imported
1110	ELOBOW, LONG 90 °15A	20	PCS	Imported
1111	PIPE SLEEVE 50A	4	PCS	Imported
1112	PIPE SLEEVE 32A	15	PCS	Imported
1113	HEAT SHRINKABLE TUBE 3MM	100	PCS	Imported
1114	HEAT SHRINKABLE TUBE 6MM	100	PCS	Imported
1115	HEAT SHRINKABLE TUBE 9MM	100	PCS	Imported
1116	GREY COATING GLOVES	300	PCS	Imported
1117	WASTE RAG(4.5 KG)	10	PCS	Imported
1118	NO.1 SEWAGE HOLDING TANK FABRICATION COMPLETE: 10M3	1	PCS	Imported
1119	NO.2 SEWAGE HOLDING TANK MATERIAL	1	PCS	Imported
1120	EXP' TANK	2	PCS	Imported
1121	FITTING	1	PCS	Imported
1122	LIFE RAFT ACCESSORIES - HYDROSTATIC RELEASE UNIT	4	PCS	Imported
1123	DECK COVERING - TEFROTEX 500 POWDER	160	PCS	Imported
1124	DECK COVERING - PORAVER LIGHT WEIGHT FILLER	26	PCS	Imported
1125	DECK COVERING - TEFROTEX 90-L POWDER	76	PCS	Imported
1126	DECK COVERING - TEFROTEX SF BONDING COAT PART A	8	PCS	Imported

Dodoma,
13th October, 2020

PHILIP .I MPANGO
Minister for Finance and Planning